

LCD DISPLAY REPAIR

avionics411.com

Millennium International Avionics provides the most cost-effective option to repair LCD display units, saving you an estimated 60% over OEM repairs! Millennium provides long-term repair and support for legacy LCD displays and will have the repair completed in as little as one day!

Millennium's custom designed automated test equipment and Class 100 clean room allows Millennium to provide a two-year warranty for all approved LCD displays. With exceptional turn times and superior support, Millennium is the best choice for your legacy avionics repair!

Millennium International Avionics can repair the following LCD displays:

- Honeywell
- Rockwell Collins
- Bendix King

Flat Rate Exchanges with absolutely NO BILL BACK!

We offer the Best Turn Time for LCD repairs in the industry!

Call 816.524.7777 or email sales@avionics411.com TODAY to schedule your repair!



Part Number	Manufacturer	Nomenclature	Description
4086850-921/922/923/924	Honeywell	737/777/717 PFD	Primary Flt Display
4082170-901 / 911 / 912	Honeywell	737/777/717 PFD	Primary Flt Display
4087440-927	Honeywell	737/777/717 PFD	Primary Flt Display
4091900-931/932/941/942/943/944	Honeywell	737/777/717 PFD	Primary Flt Display
066-50001-*	Bendix King	IVA 81A	TA/VSI TCAS Display
066-01171-*	Bendix King	IVA 81D	TA/VSI TCAS Display
066-50011-*	Bendix King	TID66A	TA/VSI TCAS Display
7013270-*	Honeywell	RM 855	LCD Radio Mgmt. Unit

Mention This Ad to Receive a

FREE

**Evaluation of
Your Display Unit.**

